



Barrie (705) 728-3026

Parts Manager: Rob McLeod - rmcLeod@lewismotorsinc.com

MC0H2250115-C15 (Interstate McBee) CAT C15 Eng Overhaul Kit (1 in stk)	\$2600.00
BX286528X (Bendix) Air Compressor (Pre 1993 DT466) (1 in stk)	\$416.00
ZJB250188451 (Chevron) Synthetic Utiptplex Grease 20L (4 in stk)	\$200.00
FLT0T63007 (Fleetrite) Surge Tank - Freightliner (1 in stk)	\$225.00
DV20350C3E (Aztec Hydraulics) Hydraulic Pump (1 in stk)	\$1500.00
C1124AL (Extreme Cam) S-Cam w/bushing kit (6 in stk)	\$140.00
K140I (Stemco) King Pin Kit (1 in stk)	\$339.00
ZJB277209983 (Chevron) Meropa 68 Gear Oil 208L (1 in stk)	\$725.00
MBL50252848 (Mobil) 10W-30 Engine Oil (6 in stk)	\$3.25
FLTST40032R (Fleetrite) 4" Round Red LED Lamp (2 in stk)	\$15.00
4309076RX (Cummins) ISX Turbocharger (1 in stk)	\$3795.00
MITFLA579 (Mitsubishi Diamondgard) Detroit Starter Motor (1in stk)	\$450.00

Bracebridge (705) 646-2677

Parts Manager: Tony Tichler - ttichler@lewismotorsinc.com

NKL-GR1680 (Klondike) Nano EP1.5 Syn Grease 15.9kg Pail (14 in stk)	\$350.00
8-97407-294-4 (Isuzu) Grill Assembly - Isuzu NPR (1 in stk)	\$459.00
ZJB235208980 (Chevron) DELO EP2 Grease 208L (1 in stk)	\$1450.00
2594141C91 (International) DOC Converter (1 in stk)	\$2700.00
3625484C92 (International) Transmission Oil Cooler (1 in stk)	\$1500.00
HOR99A8244-2 (Horton) Fan Clutch (1 in stk)	\$2700.00
C1095043 (Eaton) Solo 14" Clutch Assembly (1 in stk)	\$750.00
MITFL1179 (Mitsubishi Diamondgard) Starter Motor (1 in stk)	\$425.00
MITFLA579 (Mitsubishi Diamondgard) Starter Motor (1 in stk)	\$450.00
D1066-7972CE (Silverback) Brake Pads (2 in stk)	\$52.00
ATM12328220201 (Automann) Camshaft, L/H (1 in stk)	\$49.00
ATM12328220202 (Automann) Camshaft, R/H (1 in stk)	\$49.00

Collingwood (705) 445-2634

Parts Manager: Dave Scoville - davescoville@lewismotorsinc.com

4059025C93 (International) HX Hood Assembly (1 in stk)	\$5900.00
K931L (Stemco) King Pin Kit (1 in stk)	\$379.00
ATM157L225X825HP (Automann) Wheel - Hub Piloted 22.5 x 8 (4 in stk)	\$120.75
K80G (Stemco) King Pin Kit (1 in stk)	\$425.00
8-97173-514-2 (Isuzu) NPR/NRR/NQR Steering Box Assembly (1 in stk)	\$845.00
BX286539X (Bendix) TF-501 Detroit Air Compressor (1 in stk)	\$515.00
10461052 (Delco Remy) 42MT Starter Motor (1 in stk)	\$380.00
WAB4725001220 (Wabco) ABS Relay Valve (2 in stk)	\$480.00
FE30120 (Fleet Engineers) 5" Exhaust Diverter Box (1 in stk)	\$185.00
8-97206-760-3 (Isuzu) NPR Wheel Speed Sensor (1 in stk)	\$250.00
489XHAHXA5XK (Chelsea) Power Take Off (1 in stk)	\$650.00
26297604 (Waltco) 24" Dock Bumper (3 in stk)	\$65.00

Newmarket (905) 952-2855

Parts Manager: Kim White - kimwhite@lewismotorsinc.com

DX65030 (Dinex) Diesel oxidation Catalyst (1 in stk)	\$2205.00
HOR995547 (Horton) Fan Drive (1 in stk)	\$945.00
KL-HF8090 (Klondike) Universal Tractor Fluid - 208L (1 in stk)	\$915.00
A28440PKWHT21 (Accuride) Wheel 22.5 x 8.25 (6 in stk)	\$196.00
PFH080220 (Performance Friction) Brake Pads (6 in stk)	\$94.00
BXK056647X (Bendix) Air Compressor (1 in stk)	\$485.00
SH550026711 (Shell) H32 Hydraulic Oil - 20L (7 in stk)	\$98.00
CR1343B-100 (SKF) Oil Hub Cap (100 in stk)	\$7.95
ZJB277210451 (Chevron) Meropa 150 Gear Oil 15kg Pail (2 in stk)	\$95.00
FMH200S1 (Class Eight) Fender Mounting Kit (2 in stk)	\$195.00
8-98282-698-0 (Isuzu) NPR Cab Control Unit (1 in stk)	\$75.00
KL-HD2580 (Klondike) 0W-40 Full Syn Oil 18.9L Pail (2 in stk)	\$145.00

North Bay (705) 472-7220

Parts Manager: Steve Minor - sminor@lewismotorsinc.com

4386577 (Cummins) Water Pump (1 in stk)	\$425.00
KL-TF3980 (Klondike) SAE 40 ES Full Syn 18.9L (1 in stk)	\$205.00
LED4000H-7A (Unibond) 4" Heated Turn Signal - Amber (1 in stk)	\$29.00
LED4000H-7C (Unibond) 4" Heated Turn Signal - Clear (4 in stk)	\$29.00
R11450 (Meritor) Universal Glad Hand (22 in stk)	\$16.00
AMS65482 (Monroe) Shock Absorber (1 in stk)	\$55.00
KL-GL4080 (Klondike) Lubricant ISO 150 EP ADV (2 in stk)	\$75.00
ATM171H01501UDOE (Automann) Height Control Valve (1 in stk)	\$77.00
R803024/R803025 (Meritor) Slik Adjuster - Volvo (1 in stk of each)	\$95.00
GBH1R12538 (Goodyear) Air Spring (2 in stk)	\$125.00
3755243C92 (International) 80G L/H Fuel Tank (1 in stk)	\$375.00
4027304C93 (International) 80G R/H Fuel Tank (1 in stk)	\$375.00

Owen Sound (519) 372-2537

Parts Manager: John Sorenson - johnsorenson@lewismotorsinc.com

1878285C91 (International) Injector Assembly (1in stk)	\$800.00
KL-TF6480 (Klondike) SAE 50 TDTO-4 18.9L Pail (1 in stk)	\$105.00
ATM12210083001 (Automann) L/H Camshaft (1 in stk)	\$56.00
ATM12210083002 (Automann) R/H Camshaft (1 in stk)	\$56.00
ZBJ64111 (Grote) Utility Light (4 in stk)	\$25.00
FLTFL2593596 (Fleetrite) Fuel Injector (2 in stk)	\$560.00
DN2043 (Dieters) Sunvisor 2001+ Int 5600 (1 in stk)	\$450.00
HOR99A8656 (Horton) ISX Fan Drive (1 in stk)	\$1650.00
WAB4725002240 (Wabco) ABS Modulator Valve (1 in stk)	\$525.00
FLTFLFCASL (Fleetrite) Fog Light Assembly - F/L Cascadia (1 in stk)	\$27.00
ATM577A5341 (Automann) ABS Sensor Kit (7 in stk)	\$15.00
NKL-GR1630 (Klondike) Nano EP1.5 Grease - 14oz Tubes (126 in stk)	\$8.50

Quantities available as of November 12th, 2025. Call or visit your local Lewis Motor Sales Inc location for additional information on these discounted parts. Pricing is only valid on these parts currently in stock at its respective location. While current inventory lasts.